10/648006



Docket No.: LOREAL 3.0-056

(PATENT)

C 07 4

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Letters Patent of:

Jean-Pierre Yquel

Patent No.: 7,014,072

Issued: March 21, 2006

For: VALVE FOR A PRESSURIZED

RECEPTACLE

Certificate

MAY 0 4 2006

of Correction

Certificate of Correction Branch Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

REQUEST FOR CERTIFICATE OF CORRECTION PURSUANT TO 37 CFR 1.323

Dear Sir:

Enclosed herewith is a Certificate of Correction with respect to the above-identified U.S. Patent. You are hereby authorized to charge Deposit Account No. 12-1095 in the amount of \$100 to cover the required fee for filing a Certificate of Correction under § 1.323.

These errors were inadvertent, occurred in good faith and do not involve any changes which constitute new matter.

We look forward to early return of the Certificate of Correction duly certified.

Dated: April 27, 2006

Respectfully submitted,

05/03/2006 HDEMESS2 00000011 121095 7014072

01 FC:1811

100.00 DA

Michael H. Teschner

Registration No.: 32,862

LERNER, DAVID, LITTENBERG, KRUMHOLZ & MENTLIK, LLP

600 South Avenue West Westfield, New Jersey 07090

(908) 654-5000

Attorney for Applicant

652313_1.DOC

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.

(Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

Page _1_ of _1

PATENT NO.

1.

7,014,072

APPLICATION NO.

10/648,006

ISSUE DATE

March 21, 2006

INVENTOR(S)

Jean-Pierre Yquel

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 3, line 20, "pass" should be -- gas --.

Column 10, line 31, "tube said" should be -- tube, said --.